

Corner I.D. # 101T

MONUMENT RECORD


STATE OF INDIANA ~ COUNTY OF MONROE

Section 14, Township 7N, Range 2W,**Monument Description & Remarks:** 2-1/2" Aluminum Monument, 30" long, set 0.1' below grade.(This monument is not a PLSS corner. It was set as part of a Geodetic Control Survey.)

8/31/2016, Rachel Savich Oser, Fbk. 48, pg. 7

7/24/2018, Cassidy Raley, Fbk. 52, pg. 22

Monument recovered in good condition



I, Matthew L. Cooper, here by certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 9th day of June, 2004 A.D.

Indiana Registered Land Surveyor No. LS20200079

COMPLETED By *Steve Tankers*



0 50 100 200 Feet

ImageSource: 2014 Monroe County Pictometry



**Office of the Monroe County Surveyor
2004 Geodetic Control Project**

119 West 7th Street
Bloomington, Indiana 47404
(812) 349-2570

